



Wake County Stormwater Control Measure (SCM) Inspection Report

Wallbrook Townhomes / Approved

Complete

Planning and Development Services, Watershed Management, 336 Fayetteville St./ P.O. Box 550,
Raleigh, NC 27602

Permit Name: Wallbrook Townhomes

Permit Number: SWF-084502-2022

Inspection Status: Approved

Inspection conducted on: 9 Sep 2026 11:13 EDT

General Comments

Wet Pond A was approved on September 2, 2026
As-Built Re-Inspection for Wet Pond B only.

Inspector Joe Myers (919) 805-6384
Joe.Myers1@wake.gov

Signature of Inspector

9 Sep 2026 11:15 EDT

This SCM inspection was conducted per North Carolina Administrative Code 15A NCAC 02H & Wake County Unified Development Ordinances. Maintenance guidance is available through the North Carolina Division of Environmental Quality Stormwater Design Manual and through site specific maintenance documents recorded with the Register of Deeds Office for each stormwater device.

For more information regarding the results of this inspection, please contact Wake County Watershed Management team at 919-856-7436 or watershedmanagement@wake.gov or contact the inspector above. Wake County utilizes "Mitti" software for inspections, but does not endorse the product or company.

Inspection Details**SCM Name**

Wet Pond B

SCM type

wet pond

Stormwater conveyance condition (stormwater ditches & pipes):

Not Inspected.

Inlet to SCM condition:

Installed per plan and in good working condition.

Riprap installed per plan and functioning properly.



Photo 1



Photo 2



Photo 3



Photo 4

Forebay installed per plan and in good working condition:

Yes



Photo 5



Photo 6



Photo 7

Stabilization of areas in and around SCM:

Good



Photo 8



Photo 9



Photo 10

Riser structure condition:

good working condition



Photo 11




Photo 12



Photo 13

Emergency spillway condition:

good working condition

Condition of dam:

good working condition



Photo 14

Outfall to SCM condition:

good working condition

Outfall is stable. No signs of erosion at time of inspection.



Photo 15



Photo 16



Photo 17



Photo 18

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18