

**CMP Professional Land Surveyors**

---

Michael A. Moss, PLS L-3794, CFSNC-187  
Jason L. Panciera, PLS L-3835, CFSNC-140  
L. Jordan Parker Jr, PLS L-4685  
George T. Wrenn, Jr. PLS L-4871  
Jason E. Fowler, PLS L-5499

Telephone (919) 556-3148  
Fax (919) 554-1370

333 South White Street  
Post Office Box 1253  
Wake Forest, NC 27588-1253

March 25, 2024

**V1 response letter for FSP-24-01**

Planning & Zoning

1. Written response provided.
2. Changes clouded on pdf.
3. Revision date added to each sheet.
4. "FSP-24-01" added to each sheet.
5. Both pin #1759-99-2822 & #1850-90-6787 are old pin numbers that were part of the original boundary. With the recording of other phases, those pin numbers were removed from GIS. I have removed them from the final plats.
6. Maximum Impervious Surface allowed has been added as note #14 on sheet 1 and #3 on sheets 2 and 3.
7. The developer is aware of Street light invoice.
8. The developer is handling the Bond estimates.

Engineering

1. PDF has been updated per comments on reviewed sheet 2. Changes have been clouded.
2. The developer is handling the Bond estimates.