

2905 Meridian Parkway Durham, NC 27713 919. 361. 5000

June 24, 2025

Town of Rolesville 502 Southtown Circle P.O. Box 250 Rolesville, North Carolina 27571

RE: The Point

Case Number: FSP-25-15

Response to 1st F10 Recombination Review Comments

AWH20000

The following are the response comments for the above-mentioned project. Our response comments are in bold.

Planning & Zoning

Planning Staff

1. Provide written responses to ALL the comments received; responses should reference If/how/on what sheet was comment addressed; mark-up to mark-up is fine.

McAdams Response: Noted.

2. Bubble/cloud any revisions made – these will be removed on the final/recordable version.

McAdams Response: Noted.

3. Revise all dates on all materials – keep original/initial dates as well (build the dates).

McAdams Response: Noted.

4. Add FSP-25-15 somewhere consistent on ALL sheets.

McAdams Response: Added to each sheet.

5. Add a 1st sheet note (#9 or in a standalone text box) that describes, explains the purpose of this Recombination, including the BM/PG of the original recording of these subject lots.

McAdams Response: Please see note 1.

Engineering

Jacque Thompson & Will Fairey

1. See PDF of mark-up comments – there are about 10 entries.

McAdams Response: Noted.

FINAL PLAT 1-3

2. Please note that "Client" is Owner of the property on each sheet per: GS-47-30-c.

McAdams Response: Revised.

3. Update or remove.



McAdams Response: Filled in.

FINAL PLAT 2-3

4. Add state plane coordinates GS-47-30-f-9.

McAdams Response: Grid coordinates have been added to a corner.

5. Add curve table.

McAdams Response: See sheet 3.

6. All easement locations should be reproducible via bearing/distances and/or state plane coordinates; please address accordingly.

McAdams Response: These easements were previously recorded, so they do not need to reproduceable since the original book and page are referenced for each.

7. Update or remove.



McAdams Response: Updated.

FINAL PLAT 3-3

8. Add state plane coordinates GS-47-30-f-9.

McAdams Response: Added.

9. Add curve table GS-47-30-f.

McAdams Response: Added to sheet 3.

10. All easement locations should be reproducible via bearing/distances and/or state plane coordinates; please address accordingly.

McAdams Response: These easements were previously recorded, so they do not need to reproduceable since the original book and page are referenced for each.



11. Update or remove.



McAdams Response: Updated.

Consideration of this response is greatly appreciated. If you should have any questions or require additional information, please do not hesitate to contact me at 919. 361. 5000.

Sincerely,

McAdams

Katie Martin | Assistant Project Manager martin@mcadamsco.com | 919. 361. 5000

KM/lm

