V3 - SDP-23-03 response to V2 COR-PUD Mark-up comments

Project: Jones Dairy Storage Date: 8/1/2023

Project Number: SDP-23-03

Contact: Garrett Frank, PE, PLA

Phone: (919) 866-4503

Email: Garrett.Frank@timmons.com

Comments from the Town of Rolesville review has been addressed below. Our responses are in red.

REVIEW COMMENTS:

Sheet C4.0

- 1. The 1" FM should discharge to a cleanout at the R/W and then gravity to the MH. Response: The 1.25" forcemain now discharges to a cleanout at the R/W and then is gravity to MH4.
- 2. Please callout the RP and RPDA. You'll need to obtain a Certificate of Compliance from Raleigh's Cross Connection Program prior to issuance of building permits. Response: All proposed utility structures have been labeled see Sheet C4.0. After the site plan submittal, we will apply for the Certification of Compliance with Cross Connection.
- 3. Please provide the public sewer permit application with the next submittal. Once received, I will provide the public sewer permit number that will need to be included within the public sewer permit blocks.
 - Response: The public sewer permit application has been included in this submittal.
- 4. Please include public sewer permit blocks on cover, utility and plan/profile sheets. Response: The public sewer permit blocks have been added to the cover, utility and plan/profile sheets.
- 5. This is ultimately private but consider ending this fire line with the FH instead of this section of waterline that does not appear to be needed.
 - Response: It is best practice to end a water line with a rodded cap and thrust blocking versus dead ending a line with a fire hydrant. If additional measures or lines are needed in the future, extending the line will be easier as designed.

Sheet C4.1

- 6. Need 2/10 drop between inverts if possible.

 Response: Due to existing gas line crossing, pipes have been proposed at minimum slope with 1/10 drop. Provide 2/10 drops would create a conflict with existing gas service.
- 7. At this cover, these will have to be DIP. Response: Noted, all pipes now DIP.